


ASBESTOS INSPECTION DIAGRAM
 PROJECT #4207-04 (4800 South 1st Street)
 200 WING - WINDOW & PIPING DIAGRAM

Legend

- E1 Sample Location & Identification
- ▨ Window Caulking
- ▨ Piping Insulation (TSI Hardpack)

NOTE: ACM Hardpack TSI on Pipe Fittings is Throughout Mechanical Rooms & Assumed Throughout Building



BURCHAM ENVIRONMENTAL SERVICES, L.L.C.
 ENVIRONMENTAL CONSULTING & TESTING SERVICES
 125 S. LAKE DRIVE
 SAN MARCOS, TEXAS 78083
 PHONE: 817.396.0265
 FAX: 817.396.0190


Project Location: 4800 S. Commercial Structure, 4800 South 1st Street, Austin, Texas

Project Name: Raza Burcham

Date: 11/15/04

Page: 2 of 4

ASBESTOS INSPECTION DIAGRAM
 PROJECT #4207-04 (4800 South 1st Street)
 300 WING - WINDOW & PIPING DIAGRAM



Legend

- E1 Sample Location & Identification
- ▨ Window Caulking
- ▨ Piping Insulation (TSI Hardware)

NOTE: ACM Hardware TS on Pipe fittings is throughout Mechanical Rooms & Assumed Throughout Building

